

Inspection Report

Report No.: XYD-130825
Supplier : XY-GLOBAL

Inspection Date: 13th Sep-, 2013
Inspector: LEO

Inspection only for: PO . XYD-130825 Item No. Gear	<u>Inspection Result:</u> PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
Gear	500SET	5% inspection	0pcs	No failure	500pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 50pcs inspection.

Digital photo records :



1. Packing



2. Product:



3. Product:



4. Product:



5. Product :



6. Product:

	CNC
	AL6061 AL6065AL6063AL7075 SUS304SUS303SUS316POM
	&NBSP;
	CNC
	gague
MOQ	
/	+/- 0.01
	T / T 50T / T
	CNC CNC CNC CNC
	CNC
	20-25&NBSP; T / T 50
	CNC
1.Name OEM CNC	
2.Process CNC	
3.AL6061 AL6065AL6063AL7075POM	
4.Surface nickle	
5.Tolerance +/- 0.01	
6.100	
7.Specification OEM	
8.25-30	
9.CNC accessoried	
10.Austrial EU	
11&NBSP;ISO 9001	
ISO110	
2	
3 sureface finishment kinds available	
4	
5	
6	
7	
CNC&NBSP;	
CNC	
CNC ISO9001	
CNC	
CNC OEM	