

Inspection Report

Report No.: XYK-131019

Supplier : XY-GLOBAL

Inspection Date: 14th Nov-, 2013

Inspector: ALEX

Inspection only for: PO . XYK-131019 Item No.XY-CT-D-048	Inspection Result: PASS
--	----------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY-CT-D-048	10000PCS	0.1% inspection	0pcs	No failure	10000pcs

Appearance Inspection :
No failure,
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product:
	
3. Product:	4. Product:
	
5. Product :	6. Product:

	CNC 零件加工CNC零件加工CNC零件加工CNC零件加工CNC零件加工
	AL6061 AL6065AL6063AL7075SUS304SUS303SUS316POM
	CNC 零件加工
	gague
MOQ	
/mm	+/- 0.01mm
T / T	50T / T;
	CNC零件加工CNC零件加工CNC零件加工CNC零件加工CNC零件加工
	CNC零件加工 CNC零件加工
	20-25T / T 50
	CNC零件加工
1.Name	OEM CNC 零件加工
2.Process	CNC 零件加工
3.	AL6061 AL6065AL6063AL7075POM
4.Surface	nickle
5.Tolerance	+/- 0.01mm
6.	100mm
7.Specification	OEM 零件加工
8.	25-30mm
9.	CNC 零件加工accessoried
10.	AustrialEU
11&	NBSPISO 9001
	ISO10
2.	
3.sureface	finishmentkindlsabailable
	4
5.	
	6
7.	
	&NBSP
	ISO9001
	OEM