

Inspection Report

Report No.: XYDW-140614
Supplier: XY-GLOBAL

Inspection Date: 12th July, 2014
Inspector: Leo

Inspection only for: PO : XYDW-140614 Item No. XY33AH008	Inspection Result: PASS
---	----------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY33AH008	20000PCS	1% inspection	0pcs	No failure	20000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing



2. Product



3. Product



4 Product



5. Product:

XY-GLOBAL 深圳市真朴电子科技有限公司
XY Electronics Technology Co., Ltd

Order No.	XYDW-140614	Product Type	XY33AH008	Inspection Date	2014.7.12
Part No.	XY33AH008	Customer Name	XY Electronics Technology Co., Ltd	Inspector	Leo
Lot No.	140614	Material	XY33AH008	Quantity	20000

Inspection Item: XY33AH008
Inspection Method: 100% inspection
Inspection Result: PASS
Inspector: Leo

Inspection Date: 2014.7.12
Inspection Time: 10:00-12:00
Inspection Location: XY Electronics Technology Co., Ltd

Inspection Result: PASS
Inspector: Leo

Inspection Summary: The inspection sample plan is 100% inspection.

Inspection Report: XY Electronics Technology Co., Ltd

6. report

[illegible]