

Inspection Report

Report No.: XYWD-140609

Inspection Date: 3th July, 2014

Supplier : XY-GLOBAL

Inspector: Leo

Inspection only for: PO : XYWD-140609 Item No. XY31SY29	Inspection Result: PASS
--	----------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31SY29	30000PCS	1% inspection	0pcs	No failure	30000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :

	
1. Packing 	2. Product 
3. Product 	4 Product 
5. Product:	6. report

[illegible]