

Inspection Report

Report No.: XYAK-150416

Supplier : XY-GLOBAL

Inspection Date: 20th May, 2015

Inspector: Leo

Inspection only for: PO . XYAK-150416 Item No. XY31AL013	<u>Inspection Result:</u> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31AL013	20000PCS	1% inspection	Opes	No failure	20000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing



2. Product



3. Product



4 Product



5. Product:

[illegible]

6. report

	cnc CNC CNC CNC CNC CNC CNC CNC
	AL6061 AL6065AL6063AL7075 SUS304SUS303SUS316POM
	CNC CNC
MOQ	
/	+/- 0.01mm
T / T	50T / T
	CNC CNC CNC CNC
	CNC
	20-25 T / T 50
	CNC
1.NameOEM CNC	
2.CNC	
3.MaterialAL6061 AL6065AL6063AL7075 POM	
4.	
5. $\pm 0.01\text{mm}$	
6.100	
7.OEMserice	
8.25-30	
9.CNC	
10.AustrialEU	
11.ISO 9001	
1. ISO10	
2.	
4.	
5.	
6.	
7.	
CNC	
CNC	
CNCISO9001	
CNC	
CNC OEM	

□□CNC□□□□CNC□□□CNC□□□□□□□□

Our sales team

