

Inspection Report

Report No.: XYN-140617
Supplier : XY-GLOBAL

Inspection Date: 11th July, 2014
Inspector: Leo

Inspection only for: PO . XYN-140617 Item No.150039	<u>Inspection Result:</u> PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
150039	3000PCS	1% inspection	0pcs	No failure	3000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing



2. Product



3. Product



4 Product



5. Product:

6. Report:

[illegible]