

Inspection Report

Report No.: XYI-140302
Supplier : XY-GLOBAL

Inspection Date: 5th Apr, 2014
Inspector: Leo

Inspection only for: PO : XYI-140302 Item No.140110	<u>Inspection Result:</u> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
140110	50000PCS	1% inspection	0pcs	No failure	50000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing



2. Product



3. Product



4 Product




5. Product:



6. Product:



7. Product:



8. Report:

品名	铝合金压铸件OEM
材料	ADC12/A380
数量	1000000
公差	±0.01mm
表面处理	阳极氧化
加工工艺	CNC加工
包装方式	纸箱包装
MOQ	1000
交货期	15天
付款方式	预付30%定金，余款交货前付清
备注	
1.Name	铝合金压铸件OEM
2.Process	CNC加工
3.	ADC12/A380
4.Surface	阳极氧化
5.Tolerance	±0.01mm
6.	1000000
7.Specification	OEM
8.	25-30天
9.	accessoried
10.	Austrial EU
11&NBSP	ISO 9001
品名	
ISO	1000000
2.	
3.sureface	finishment kinds available
品名	4.
5.	
品名	6.
7.	
品名	
品名	&NBSP
品名	
品名	ISO9001
品名	
OEM	