

Inspection Report

Report No.: XYDA-140505
Supplier : XY-GLOBAL

Inspection Date: 1th Jun, 2014
Inspector: Leo

Inspection only for: PO . XYDA-140505 Item No.1490216	<u>Inspection Result:</u> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
1490216	20000PCS	1% inspection	0pcs	No failure	20000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing



2. Product



3. Product



4 Product



5. Product:



6. Product:

Part Name	Part Name OEM Part Name
Material	Material ADC12/A380
Surface	Surface
Process	Process
MOQ	MOQ
Tolerance	Tolerance +/- 0.01
Lead Time	Lead Time T / T 50 T / T
CNC	CNC
Accessories	Accessories
2025 T / T 50	2025 T / T 50
1.Name	1.Name OEM
2.Process	2.Process CNC
3.Material	3.Material ADC12/A380
4.Surface	4.Surface nickle
5.Tolerance	5.Tolerance +/- 0.01
6	6
7.Specification	7.Specification OEM service
8	8
9	9
10	10
11	11
ISO 9001	ISO 9001
1. 10	1. 10
2	2
3. sureface	3. sureface finishment
4	4
5	5
6	6
7	7
ISO9001	ISO9001
OEM	OEM