

Inspection Report

Report No.: XYS-130721
Supplier : XY-GLOBAL

Inspection Date: 25th Aug, 2013
Inspector: Leo

Inspection only for: PO . XYS-130721 Item No.XY-1634200	<u>Inspection Result:</u> PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY-1634200	500PCS	5% inspection	0pcs	No failure	500pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing



2. Product



3. Product



4 Product



5. Product:



6. Product:

ชื่อ	บริษัท ออโต้แมติกแมชีน จำกัด OEM/ODM
ชื่อสินค้า	ADC12/A380
ชื่อ	ชื่อ
ชื่อ	ชื่อ
ชื่อ	CNC
ชื่อ	CNC
ชื่อ	ชื่อ
MOQ	ชื่อ
ชื่อ/ชื่อ	+/- 0.01
ชื่อ	T / T 50% T / T
ชื่อ	CNC
ชื่อ	ชื่อ
ชื่อ	ชื่อ
ชื่อ	20-25 T / T 50%
ชื่อ	ชื่อ
1.Name	OEM
2.Process	CNC
3.	ADC12/A380
4.Surface	nickle
5.Tolerance	+/- 0.01
6.	100
7.Specification	OEM
8.	25-30
9.	accessoried
10.	Austrial/EU
11&NBSP	ISO 9001
ชื่อ	ชื่อ
ISO	1/10
2.	ชื่อ
3.sureface	finishment kinds available
ชื่อ	4
5.	ชื่อ
ชื่อ	6
7.	ชื่อ
ชื่อ	ชื่อ
ชื่อ	&NBSP
ชื่อ	ชื่อ
ชื่อ	ISO9001
ชื่อ	ชื่อ
OEM	ชื่อ