XY-GLOBAL **XY Electronics Technology Co., Ltd**

Inspection Report

Report No.: XYBA-140922 **Inspection** Date:18th- Oct-, 2014
Supplier : **XY-GLOBAL** **Inspector:**LEO

Inspection only for:	**Inspection Result:**
PO . XYBA-140922 Item No. XY21ZC015	**PASS**

Description	**Finished Q'ty**	**Sample Size**	**Defect Found**	**Defects Description**	**Acceptable Q'ty**
XY21ZC015	**1200Set**	7% inspection	0pcs	No failure	2000Set

Appearance Inspection :
No failure,
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :

1. Packing

2. Product:

3. Product:

4. Product:

5. Product :



6. Inspection report:

□□□□□	CNC □□□□□□□□□□□□□□□□□□□□CNC□□□□□□□□□□□□□□□□□□□□ □□□□□□□□□□□□□□□□CNC□□□□□□□□□□CNC□□□□□□□□□□CNC□□□□□□□□□□□□□□□□□□□□□□□□□□□□CNC□□□□□□CNC
□□□□□	□□□□□□□AL6061 AL6065□AL6063□AL7075□SUS304□SUS303□SUS316□POM□□
□□□	□□□□□□□□□□□□□□
□□□□	□□□□□□□□□ □□□□□□□□□□□□□□□□□□□□