

Inspection Report

Report No.: XYNK-130819

Supplier : XY-GLOBAL

Inspection Date: 15th Sep., 2013

Inspector: LEO

Inspection only for:	<u>Inspection Result:</u>
PO : XYNK-130819 Item No. 1401200	PASS

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
1401200	1000PCS	100% inspection	0pcs	No failure	1000pcs

Appearance Inspection :

No failure.

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing



2. Product:



3. Product:



4. Product:



5. Product :



6. Product:

[illegible]