

Inspection Report

Report No.: XYAK-130819

Supplier : XY-GLOBAL

Inspection Date:15th Sep-, 2013

Inspector:LEO

Inspection only for:	Inspection Result:
PO . XYAK-130819 Item No.2500247	PASS

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
2500247	3000PCS	100% inspection	0pcs	No failure	3000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.


Digital photo records :



1. Packing



2. Product:



3. Product:



4. Product:



5. Product :



6. Product:

[illegible]