

Inspection Report

Report No.: XYGA-150320

Supplier : XY-GLOBAL

Inspection Date: 23th Apr-, 2015

Inspector: LEO

Inspection only for: PO . XYGA-140320 Item No. XY21ZC057	<u>Inspection Result:</u> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY21ZC057	8000pcs	7% inspection	0pcs	No failure	8000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing

2. Product:



3. Product:

4. Product:

[illegible]

5. Product :

6. Inspection report:

	CNC CNC CNC CNC CNC CNC CNC CNC CNC CNC
	AL6061 AL6065AL6063AL7075 SUS304SUS303SUS316POM
	CNC CNC
	gague
MOQ	
/	+/- 0.01
	T / T 50T / T :
	CNC CNC CNC CNC
	CNC
	2025 T / T 50
	CNC
1.NameOEM CNC	
2.ProcessCNC	
3.MaterialAL6061 AL6065AL6063AL7075 POM	
4.Surfacenickle	
5.Tolerance+/- 0.01	
6.100	
7.SpecificationOEMserice	
8.2530	
9.CNCaccessoried	
10.AustrialEU	
11.ISO 9001	
ISO1. 10	
2.	
3.surefacefinishmentkindlsavailable	
4.	
5.	
6.	
7.	
CNC	
CNC	
CNCISO9001	
CNC	
CNCOEM	