

Inspection Report

Report No.: XYAN-150407

Supplier : XY-GLOBAL


Inspection Date: 5th May-, 2015

Inspector: LEO

Inspection only for:	Inspection Result:
PO : XYAN-150407 Item No. XY21ZC075	PASS

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY21ZC075	8000pcs	7% inspection	0pcs	No failure	8000pcs

Appearance Inspection :
No failure,
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product:
	
3. Product:	4. Product:
	
5. Product :	6. Inspection report:

[illegible]

Customer's Feedback



Dear Ivy,

I am very satisfied with Scott and I feel it's a great cooperation between XY Global and GST. I hope we can continue in such a perfect way in future.

Yours sincerely

Nicole Holtschke
Einkauf / Purchasing

01
OPTION



Hi Ivy,

Thanks for your email.

Jack is providing me with excellent service and I have been very happy with what you produce.

We hope to work long term with you also but my business partner has asked for other quotes before we make the next batch of products.

Still waiting to get them all back. Thank you!

Regards,
Scott James | Director

02
OPTION



Dear Ivy,

I am happy and no problem dealing with Scott, hope will keep good cooperation and relationship with your esteemed company.

Thanks
Regards
Siao

03
OPTION



Hello Ivy,

Naky has always been very responsive and met our requirements well.

I have no problem doing business with XY-Global.

Kind Regards
Keith



04
OPTION



Dear Ivy,

thank you for reaching out.

we are happy to work with nancy and looking forward to a long term cooperation.

best,

Sigmar Berg

05
OPTION