





XY Electronics Technology Co., Ltd

## Inspection Report

Report No.: XYK-130829  
Supplier : XY-GLOBAL

Inspection Date: 29<sup>th</sup> Sep-, 2013  
Inspector: LEO

|                                                              |                                   |
|--------------------------------------------------------------|-----------------------------------|
| Inspection only for:<br>PO . XYK-130829      Item No.1330026 | <u>Inspection Result:</u><br>PASS |
|--------------------------------------------------------------|-----------------------------------|

| Description | Finished Q'ty | Sample Size     | Defect Found | Defects Description | Acceptable Q'ty |
|-------------|---------------|-----------------|--------------|---------------------|-----------------|
| 1330026     | 50PCS         | 100% inspection | 0pcs         | No failure          | 50pcs           |

**Appearance Inspection :**

No failure,

**Dimension Inspection:**

No failure , below measurement report for reference.

**Assembly Test:**

No failure

**Inspection Summary**

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing



2. Product:



3. Product:



4. Product:



5. Product :



6. Product:

[illegible]