

Inspection Report

Report No.: XYKB-140521
Supplier : XY-GLOBAL

Inspection Date: 15th Jun, 2014
Inspector: Leo

Inspection only for: PO . XYKB-140521 Item No. XY72YM017	Inspection Result: PASS
---	----------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY72YM017	1000PCS	1% inspection	0pcs	No failure	1000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :

	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. Dimensions report:

Company Name	Shenzhen Hengsheng Precision Technology Co., Ltd. OEM/ODM service available
Product Name	ADC12/A380
Material	Aluminum
Surface Treatment	Anodizing / Electroplating
Process	CNC Machining
MOQ	1000 pieces
Lead Time	+/- 0.01mm
Tolerance	T / T 50% / T 50%
Payment Terms	CNC Machining / CNC Machining
Quality Control	100% inspection before shipping
Shipping Method	By Air / By Sea
Delivery Time	20-25 days / T 50%
Warranty	1 Year
1. Name: Hengsheng Precision Technology Co., Ltd.	
2. Process: CNC Machining	
3. Material: ADC12/A380	
4. Surface: Anodizing / Electroplating	
5. Tolerance: +/- 0.01mm	
6. MOQ: 1000 pieces	
7. Specification: OEM/ODM service available	
8. Lead Time: 25-30 days	
9. Accessory: Accessory available	
10. Certification: Austrial / EU	
11. ISO 9001	
ISO 9001:2015	
2. sureface finishment: kinds available	
4. Lead Time	
5. MOQ	
6. Lead Time	
7. Certification	
ISO 9001	
OEM/ODM service available	