

Inspection Report

Report No.: XYDS-140618

Inspection Date: 15th July, 2014

Supplier : XY-GLOBAL

Inspector: Leo

Inspection only for: PO : XYDS-140618 Item No.801-30-210	<u>Inspection Result:</u> PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
801-30-210	10000PCS	1% inspection	0pcs	No failure	10000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :

			
1. Packing		2. Product	
			
3. Product		4 Product	
			
5. Product:		6. Product	

[illegible]