

Inspection Report

Report No.: XYNK-130813

Supplier : XY-GLOBAL

Inspection Date: 7th Sep-, 2013

Inspector: LEO

Inspection only for: PO : XYNK-130813 Item No.1390257	Inspection Result: PASS
---	----------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
1390257	5000PCS	100% inspection	0pcs	No failure	5000pcs

Appearance Inspection :
No failure,
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product:
	
3. Product:	4. Product:
	
5. Product :	6. Product:

	CNC
	AL6061 AL6065AL6063AL7075SUS304SUS303SUS316POM
	CNC
	gague
MOQ	
/	+/- 0.01
	T / T 5050T / T ;
	CNC CNC CNC CNC
	CNC
	20-25T / T 50
	CNC
1.Name OEM CNC	
2.Process CNC	
3.MaterialAL6061 AL6065AL6063AL7075POM	
4.Surface nickle	
5.Tolerance +/- 0.01	
6 100	
7.SpecificationOEMserice	
8. 2530	
9. CNC accessoried	
10. AustrialEU	
11. ISO 9001	
ISO1. 10	
2.	
3. surefacefinishment kindlsavailable	
4	
5.	
6.	
7.	
CNC	
CNC	
CNCISO9001	
CNC	
CNC OEM	