

Inspection Report

Report No.: XYDA-140504

Inspection Date: 1st Jun, 2014

Supplier : XY-GLOBAL

Inspector: Leo

Inspection only for:	<u>Inspection Result:</u>
PO : XYDA-140504 Item No.1493768	PASS

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
1493768	15000PCS	1% inspection	0pcs	No failure	15000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing

2. Product



3. Product

4 Product



5. Product:

6. Product:

[illegible]