



XY Electronics Technology Co., Ltd

Inspection Report

Report No.: XYN-130818

Supplier : XY-GLOBAL

Inspection Date: 10th Sep, 2013

Inspector: LEO

Inspection only for:
PO : XYD-130813 Item No. XY-CT-D-049

Inspection Result:
PASS

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY-CT-D-049	6000PCS	1% inspection	0pcs	No failure	6000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing



2. Product:



3. Product:



4. Product:



5. Product :



6. Product:

	CNC CNC CNC CNC
	AL6061 AL6065AL6063AL7075 &NBSP; SUS304SUS303SUS316POM
	CNC
	gague
MOQ	
/	+/- 0.01
	T / T 50 50T / T;
	CNC CNC CNC CNC
	CNC
	20-25&NBSP;T / T 50
	CNC
1.Name OEM CNC	
2.Process CNC	
3. AL6061 AL6065AL6063AL7075POM	
4.Surface nickle	
5.Tolerance +/- 0.01	
6 100	
7.Specification OEM	
8 25-30	
9 CNC accessoried	
10 Austrial EU	
11&NBSP;ISO 9001	
ISO 110	
2	
3 sureface finishment kindls abailable	
4	
5	
6	
7	
CNC&NBSP;	
CNC	
CNCISO9001	
CNC	
CNC OEM	