

Inspection Report

Report No.: XYSK-140623

Supplier: XY-GLOBAL

Inspection Date: 15th July, 2014

Inspector: Leo

Inspection only for:	Inspection Result:
PO: XYSK-140623 Item No. XY31SY020	PASS

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31SY020	20000PCS	1% inspection	0pcs	No failure	20000pcs

Appearance Inspection:

No failure,

Dimension Inspection:

No failure, below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records:



1. Packing

2. Product



3. Product

4 Product



XY-GLOBAL 深圳市真朴电子科技有限公司
XY Electronics Technology Co., Ltd

Inspection Report

Product Name: XY31SY020
Product Type: XY31SY020
Inspection Date: 2014.07.15
Inspector: Leo

Inspection Item: XY31SY020
Inspection Method: 100% inspection
Inspection Result: PASS

Inspection Details:

Item	Requirement	Actual	Result
1. Appearance	1.1. No visible defects	1.1. No visible defects	Pass
2. Dimension	2.1. No visible defects	2.1. No visible defects	Pass
3. Assembly	3.1. No visible defects	3.1. No visible defects	Pass
4. Test	4.1. No visible defects	4.1. No visible defects	Pass

Inspection Summary: The inspection sample plan is 100% inspection. The inspection result is PASS.

5. Product:

6. report

	CNC
	AL6061 AL6065AL6063AL7075SUS304SUS303SUS316POM
	CNC
	gague
MOQ	
/	+/- 0.01
	T / T 50 50T / T;
	CNC CNC CNC CNC
	CNC
	20-25T / T 50
	CNC
1.Name OEM CNC	
2.Process CNC	
3.MaterialAL6061 AL6065AL6063AL7075 POM	
4.Surface nickle	
5.Tolerance +/- 0.01	
6 100	
7.SpecificationOEMserice	
8. 2530	
9. CNC accessoried	
10. AustrialEU	
11. ISO 9001	
ISO1. 10	
2.	
3. surefacefinishment kindlsavailable	
4.	
5.	
6.	
7.	
CNC	
CNC	
CNCISO9001	
CNC	
CNCOEM	