

Inspection Report

Report No.: XYN-140521
Supplier : XY-GLOBAL

Inspection Date: 16th Jun, 2014
Inspector: Ken

| | |
|---|-----------------------------------|
| Inspection only for: PO . XYN-140521 Item No.XY-142037 | Inspection Result: PASS |
|---|-----------------------------------|

| Description | Finished Q'ty | Sample Size | Defect Found | Defects Description | Acceptable Q'ty |
|-------------|----------------|---------------|--------------|---------------------|-----------------|
| XY-142037 | 8000PCS | 1% inspection | 0pcs | No failure | 8000pcs |

| |
|--|
| Appearance Inspection : |
| No failure. |
| Dimension Inspection: |
| No failure , below measurement report for reference. |
| Assembly Test: |
| No failure |
| Inspection Summary |
| The inspection sample plan is 100% inspection. |

| | |
|---|--|
| Digital photo records : | |
|  |  |
| 1. Packing | 2. Product |
|  |  |
| 3. Product | 4 Product |
|  |  |
| 5. Product: | 6. Report: |

