

Inspection Report

Report No.: XYKB-140502
Supplier : XY-GLOBAL

Inspection Date: 1th Jun, 2014
Inspector: Leo

Inspection only for: PO . XYKB-140502 Item No. XY72YM021	<u>Inspection Result:</u> PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY72YM021	180000PCS	1% inspection	0pcs	No failure	180000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing

2. Product



3. Product

4 Product



5. Product:

6. Product:

[illegible]