

Inspection Report

Report No.: XYLA-150315
Supplier : XY-GLOBAL

Inspection Date: 18th Apr, 2015
Inspector: Leo

Inspection only for: PO : XYLA-150315 Item No. XY31PC011	<u>Inspection Result:</u> PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31PC011	25000PCS	1% inspection	0pcs	No failure	25000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing



2. Product



3. Product



4 Product



5. Product:

Item	Spec	Actual	Unit	Result
1	1.0000	1.0000	mm	OK
2	1.0000	1.0000	mm	OK
3	1.0000	1.0000	mm	OK
4	1.0000	1.0000	mm	OK
5	1.0000	1.0000	mm	OK
6	1.0000	1.0000	mm	OK
7	1.0000	1.0000	mm	OK
8	1.0000	1.0000	mm	OK
9	1.0000	1.0000	mm	OK
10	1.0000	1.0000	mm	OK
11	1.0000	1.0000	mm	OK
12	1.0000	1.0000	mm	OK
13	1.0000	1.0000	mm	OK
14	1.0000	1.0000	mm	OK
15	1.0000	1.0000	mm	OK
16	1.0000	1.0000	mm	OK
17	1.0000	1.0000	mm	OK
18	1.0000	1.0000	mm	OK
19	1.0000	1.0000	mm	OK
20	1.0000	1.0000	mm	OK
21	1.0000	1.0000	mm	OK
22	1.0000	1.0000	mm	OK
23	1.0000	1.0000	mm	OK
24	1.0000	1.0000	mm	OK
25	1.0000	1.0000	mm	OK
26	1.0000	1.0000	mm	OK
27	1.0000	1.0000	mm	OK
28	1.0000	1.0000	mm	OK
29	1.0000	1.0000	mm	OK
30	1.0000	1.0000	mm	OK
31	1.0000	1.0000	mm	OK
32	1.0000	1.0000	mm	OK
33	1.0000	1.0000	mm	OK
34	1.0000	1.0000	mm	OK
35	1.0000	1.0000	mm	OK
36	1.0000	1.0000	mm	OK
37	1.0000	1.0000	mm	OK
38	1.0000	1.0000	mm	OK
39	1.0000	1.0000	mm	OK
40	1.0000	1.0000	mm	OK
41	1.0000	1.0000	mm	OK
42	1.0000	1.0000	mm	OK
43	1.0000	1.0000	mm	OK
44	1.0000	1.0000	mm	OK
45	1.0000	1.0000	mm	OK
46	1.0000	1.0000	mm	OK
47	1.0000	1.0000	mm	OK
48	1.0000	1.0000	mm	OK
49	1.0000	1.0000	mm	OK
50	1.0000	1.0000	mm	OK
51	1.0000	1.0000	mm	OK
52	1.0000	1.0000	mm	OK
53	1.0000	1.0000	mm	OK
54	1.0000	1.0000	mm	OK
55	1.0000	1.0000	mm	OK
56	1.0000	1.0000	mm	OK
57	1.0000	1.0000	mm	OK
58	1.0000	1.0000	mm	OK
59	1.0000	1.0000	mm	OK
60	1.0000	1.0000	mm	OK
61	1.0000	1.0000	mm	OK
62	1.0000	1.0000	mm	OK
63	1.0000	1.0000	mm	OK
64	1.0000	1.0000	mm	OK
65	1.0000	1.0000	mm	OK
66	1.0000	1.0000	mm	OK
67	1.0000	1.0000	mm	OK
68	1.0000	1.0000	mm	OK
69	1.0000	1.0000	mm	OK
70	1.0000	1.0000	mm	OK
71	1.0000	1.0000	mm	OK
72	1.0000	1.0000	mm	OK
73	1.0000	1.0000	mm	OK
74	1.0000	1.0000	mm	OK
75	1.0000	1.0000	mm	OK
76	1.0000	1.0000	mm	OK
77	1.0000	1.0000	mm	OK
78	1.0000	1.0000	mm	OK
79	1.0000	1.0000	mm	OK
80	1.0000	1.0000	mm	OK
81	1.0000	1.0000	mm	OK
82	1.0000	1.0000	mm	OK
83	1.0000	1.0000	mm	OK
84	1.0000	1.0000	mm	OK
85	1.0000	1.0000	mm	OK
86	1.0000	1.0000	mm	OK
87	1.0000	1.0000	mm	OK
88	1.0000	1.0000	mm	OK
89	1.0000	1.0000	mm	OK
90	1.0000	1.0000	mm	OK
91	1.0000	1.0000	mm	OK
92	1.0000	1.0000	mm	OK
93	1.0000	1.0000	mm	OK
94	1.0000	1.0000	mm	OK
95	1.0000	1.0000	mm	OK
96	1.0000	1.0000	mm	OK
97	1.0000	1.0000	mm	OK
98	1.0000	1.0000	mm	OK
99	1.0000	1.0000	mm	OK
100	1.0000	1.0000	mm	OK

6. report

[illegible]

Safety is our serious job for our worker and engineer team

