

Inspection Report

Report No.: XYI-130801

Inspection Date: 03th Sep, 2013

Supplier : XY-GLOBAL

Inspector: LEO

Inspection only for: PO : XYI-130801 Item No. 1400354	<u>Inspection Result:</u> PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
1400354	50000PCS	1% inspection	0pcs	No failure	50000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing



2. Product:



3. Product:



4. Product:



5. Product :



6. Product:

	CNC CNC CNC CNC CNC CNC CNC
	AL6061 AL6065 AL6063 AL7075 &NBSP SUS304 SUS303 SUS316 POM
	CNC
	gague
MOQ	
/	+/- 0.01
	T / T 50 50 T / T:
	CNC CNC CNC CNC
	CNC
	20-25&NBSP T / T 50
	CNC
1.Name	OEM CNC
2.Process	CNC
3. AL6061 AL6065 AL6063 AL7075 POM	
4.Surface	nickle
5.Tolerance	+/- 0.01
6	100
7.Specification	OEM
8	25-30
9	CNC accessoried
10	Austrial EU
11&NBSP	ISO 9001
ISO 1 10	
2	
3 sureface finishment	kindls abailable
4	
5	
6	
7	
CNC &NBSP	
CNC	
CNC ISO9001	
CNC	
CNC OEM	