

Inspection Report

Report No.: XYAD-140516
Supplier : XY-GLOBAL

Inspection Date: 25th Jun, 2014
Inspector: Leo

Inspection only for: PO : XYAD-140516 Item No.200-10-870	Inspection Result: PASS
---	----------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
200-10-870	20000PCS	1% inspection	0pcs	No failure	20000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing

2. Product



3. Product

4 Product



5. Product:

6. Product:

[illegible]