

Inspection Report

Report No.: XYI-140320
Supplier : XY-GLOBAL

Inspection Date: 17th Apr, 2014
Inspector: Leo

Inspection only for: PO : XYI-140320 Item No.142089	Inspection Result: PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
142089	40000PCS	1% inspection	0pcs	No failure	40000pcs

Appearance Inspection :

No failure.

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :




1. Packing




2. Product




3. Product




4 Product



5. Product:



6. Product:



7. Product:

8. Report:

項目	詳細なOEM仕様を記載してください
部品名	ADC12 A380
材質	アルミニウム
用途	自動車用エンジン部品
仕様	CNC加工による精密加工
公差	±0.01mm
MOQ	100個
納期	受注後2週間以内
検査	100%検査を実施します
包装	個別に保護フィルムを貼付し、ダンボール箱に梱包します
1.Name	詳細なOEM仕様を記載してください
2.Process	CNC加工
3.部品名	ADC12 A380
4.Surface	表面処理はニッケルメッキです
5.Tolerance	±0.01mm
6.数量	100個
7.Specification	OEM仕様を記載してください
8.寸法	25-30mm
9.付属品	accessories (必要に応じて)
10.認証	Austrian EU
11.&NBSP	ISO 9001
ISO	10mm
2.表面	finishment (kindly available)
3.表面	4mm
5.表面	6mm
7.表面	6mm
ISO	ISO 9001
OEM	OEM仕様を記載してください