



XY Electronics Technology Co., Ltd

Inspection Report

Report No.: 140607-V1
Supplier : XY-GLOBAL

Inspection Date: 7th Jun- 2014
Inspector: Leo

Inspection only for: PO . XYS-140519 Item No. Gadget	Inspection Result: PASS
---	----------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
purple artware box	6000	1% inspection	0pcs	No failure	6000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing



2. Packing



3. Product



4 Product



5. Product



6. Product

	CNC
	AL6061 AL6065AL6063AL7075 SUS304SUS303SUS316POM
	CNC
	gague
MOQ	
/	+/- 0.01
	T / T 50 50T / T;
	CNC CNC CNC CNC
	20-25 T / T 50
	CNC
1.Name OEM CNC	
2.Process CNC	
3. AL6061 AL6065AL6063AL7075POM	
4.Surface nickle	
5.Tolerance +/- 0.01	
6 100	
7.Specification OEM	
8 25-30	
9 CNC accessoried	
10 Austrial EU	
11 ISO 9001	
ISO 1 10	
2	
3 sureface finishment kindls available	
4	
5	
6	
7	
CNC &NBSP	
CNC	
CNC ISO9001	
CNC	
CNC OEM	