

Inspection Report

Report No.: XYBA-140906

Supplier : XY-GLOBAL

Inspection Date: 1th Oct-, 2014

Inspector:LEO

Inspection only for: PO . XYBA-140906 Item No. XY21ZC004	<u>Inspection Result:</u> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY21ZC004	800PCS	7% inspection	0pcs	No failure	800pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure, below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing

2. Product



3. Product:

4. Product:



XY-6L BAL 深圳市西谷村电子科技有限公司
 XY Electronics Technology Co., Ltd.

Pin 1: VDD
 Pin 2: VDD
 Pin 3: VDD
 Pin 4: VDD
 Pin 5: VDD
 Pin 6: VDD
 Pin 7: VDD
 Pin 8: VDD
 Pin 9: VDD
 Pin 10: VDD
 Pin 11: VDD
 Pin 12: VDD
 Pin 13: VDD
 Pin 14: VDD
 Pin 15: VDD
 Pin 16: VDD

5. Product :

6. Inspection report:

	CNC
	AL6061 AL6065AL6063AL7075SUS304SUS303SUS316POM
	CNC
	gague
MOQ	
/	+/- 0.01
	T / T 50 50T / T;
	CNC CNC CNC CNC
	CNC
	20-25T / T 50
	CNC
1.Name	OEM CNC
2.Process	CNC
3.Material	AL6061 AL6065AL6063AL7075 POM
4.Surface	nickle
5.Tolerance	+/- 0.01
6.	100
7.Specification	OEMserice
8.	2530
9.	CNC accessoried
10.	AustrialEU
11.	ISO 9001
ISO	1. 10
2.	
3. sureface	finishment kindsavailable
	4.
5.	
	6.
7.	
CNC	
CNC	
CNC	ISO9001
CNC	
CNC	OEM