

Inspection Report

Report No.: XYKS-140605
Supplier : XY-GLOBAL

Inspection Date: 2th July, 2014
Inspector: Leo

Inspection only for: PO : XYSK-140605 Item No. XY31SY50	Inspection Result: PASS
---	----------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31SY50	6000PCS	1% inspection	0pcs	No failure	6000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing



2. Product



3. Product



4 Product



5. Product:

XY-GLOBAL 深圳市真朴电子科技有限公司
XY Electronics Technology Co., Ltd

Inspection Report Form

Product Name: XY31SY50 Part No: XY31SY50 Revision: 1.0

Inspector: Leo Date: 2014-07-02

Inspection Result: PASS

Inspection Method: 100% inspection

Inspection Location: XY Electronics Technology Co., Ltd

Inspection Equipment: Vernier Caliper

Inspection Environment: 23±2°C, 50%~70% RH

Inspection Process: 1. Visual inspection 2. Dimensional inspection 3. Assembly inspection

Inspection Results: 1. Visual inspection: No failure 2. Dimensional inspection: No failure 3. Assembly inspection: No failure

Inspection Conclusion: The inspection results are satisfactory. The product meets the requirements of the drawing and the inspection plan.

Inspector: Leo Date: 2014-07-02

6. report

[illegible]

Safety is our serious job for our worker and engineer team

