

Inspection Report

Report No.: XYI-140307
Supplier : XY-GLOBAL

Inspection Date: 5th Apr, 2014
Inspector: Leo

Inspection only for: PO : XYI-140307 Item No.140207	<u>Inspection Result:</u> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
140207	30000PCS	1% inspection	0pcs	No failure	30000pcs

Appearance Inspection :

No failure.

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing



2. Product



3. Product



4 Product



5. Product:



6. Product:



7. Product:

8. Report:

	OEM
	ADC12A380
	CNC
	CNC
	gague
MOQ	
/	+/- 0.01
	T / T 50
	CNC
	20-25T / T 50
1.Name	OEM
2.Process	CNC
3.	ADC12A380
4.Surface	nickle
5.Tolerance	+/- 0.01
6.	100
7.Specification	OEM
8.	25-30
9.	accessoried
10.	AustrialEU
11&NBSP	ISO 9001
ISO	110
2.	
3.surefacefinishment	kindlsavailable
	4
5.	
	6
7.	
&NBSP	
	ISO9001
OEM	