

□□□CNC□□□□



XY Electronics Technology Co., Ltd

Inspection Report

Report No.: XYK-130819

Inspection Date: 25th Sep-, 2013

Supplier : XY-GLOBAL

Inspector: LEO

Inspection only for:	<u>Inspection Result:</u>
PO : XYK-130819 Item No. 1330025	PASS

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
1330025	50PCS	100% inspection	0pcs	No failure	50pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure


Inspection Summary

The inspection sample plan is 100% inspection.


Digital photo records :




1. Packing




2. Product:



3. Product:



4. Product:



5. Product :



6. Product:

[illegible]