

Inspection Report

Report No.: XYGA-150316

Supplier : XY-GLOBAL

Inspection Date: 18th Apr-, 2015

Inspector:LEO

Inspection only for:	<u>Inspection Result:</u>
PO . XYGA-140316 Item No. XY21ZC055	PASS

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY21ZC055	8000pcs	7% inspection	0pcs	No failure	8000pcs

Appearance Inspection :

No failure.

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing

2. Product:



3. Product:

4. Product:

[illegible]

100

5. Product :

6. Inspection report:

[illegible]