

Inspection Report

Report No.: XYDA-150314
Supplier: XY-GLOBAL

Inspection Date: 8th Apr, 2015
Inspector: Leo

Inspection only for: PO: XYDA-150314 Item No. XY31CY032	Inspection Result: PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31CY032	35000PCS	1% inspection	0pcs	No failure	35000pcs

Appearance Inspection:

No failure,

Dimension Inspection:

No failure, below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records:



1. Packing

2. Product



3. Product

4 Product



XY-GLOBAL 深圳市真朴电子科技有限公司
XY Electronics Technology Co., Ltd

Inspection Report	Product Name	Inspection Date	Inspector
XYDA-150314	XY31CY032	2015.04.08	Leo
Part Name	Part Number	Lot Number	Quantity
XY31CY032	XY31CY032	XY31CY032	35000
Inspection Item	Inspection Method	Inspection Result	Inspection Conclusion
Appearance	Visual	Pass	Pass
Dimension	Caliper	Pass	Pass
Assembly	Assembly	Pass	Pass
Test	Test	Pass	Pass
Storage	Storage	Pass	Pass
Transportation	Transportation	Pass	Pass
Usage	Usage	Pass	Pass
Disposal	Disposal	Pass	Pass
Recycling	Recycling	Pass	Pass
Other	Other	Pass	Pass

Inspector: Leo
Date: 2015.04.08
Signature: _____

5. Product:

6. report

[illegible]