

Inspection Report



Report No.: XYD-140514
Supplier : XY-GLOBAL

Inspection Date: 10th Jun, 2014
Inspector: Leo

Inspection only for: PO . XYD-140514 Item No.XY-141124	<u>Inspection Result:</u> PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY-141124	20000PCS	1% inspection	0pcs	No failure	20000pcs

Appearance Inspection :
No failure.
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. Report:

ชื่อ	บริษัท อดิเรกอินเตอร์เทรด จำกัด ผลิตและจำหน่ายสินค้า OEM
รุ่น	รุ่น ADC12 A380
สี	สี สด
ขนาด	ขนาด มาตรฐาน
วัสดุ	วัสดุ มาตรฐาน
กระบวนการ	CNC มาตรฐาน
MOQ	MOQ 1000
ราคา/ชิ้น	+/- 0.01
ระยะเวลา	T / T 50% T / T 50%
สถานที่	CNC มาตรฐาน
การรับประกัน	การรับประกัน 1 ปี
ชื่อ	ชื่อ บริษัท
ชื่อ	20-25 T / T 50%
ชื่อ	ชื่อ บริษัท
1.Name	1.Name บริษัท OEM
2.Process	2.Process มาตรฐาน CNC
3.รุ่น	3.รุ่น ADC12 A380
4.Surface	4.Surface มาตรฐาน nicle
5.Tolerance	5.Tolerance +/- 0.01
6.ขนาด	6.ขนาด 100
7.Specification	7.Specification OEM
8.ระยะเวลา	8.ระยะเวลา 25-30
9.การรับประกัน	9.การรับประกัน 1 ปี
10.มาตรฐาน	10.มาตรฐาน Austrial EU
11. 	11. ISO 9001
ชื่อ	ชื่อ บริษัท
ISO	ISO 10
2	2
3 sureface	3 sureface finishment kinds available
4	4
5	5
6	6
7	7
ชื่อ	ชื่อ บริษัท
 	
ชื่อ	ชื่อ บริษัท
ISO9001	ISO9001
OEM	OEM