

Inspection Report

Report No.: XYND-140512

Inspection Date: 5th Jun, 2014

Supplier : XY-GLOBAL

Inspector: Leo

Inspection only for: PO . XYND-140512 Item No.30013467	<u>Inspection Result:</u> PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
30013467	10000PCS	1% inspection	0pcs	No failure	10000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :

			
1. Packing		2. Product	
			
3. Product		4 Product	
			
5. Product:		6. Product:	

Company Name	Shenzhen Hengsheng Precision Technology Co., Ltd. OEM/ODM service available
Product Name	ADC12/A380
Material	Aluminum
Surface Treatment	Anodizing / Electroplating / Powder Coating
Process	CNC Machining
MOQ	1000 pieces
Lead Time	15-20 days
Payment Terms	T/T, L/C, Western Union
Quality Control	ISO 9001:2015
Shipping Method	By Air / By Sea
1.Name	Shenzhen Hengsheng Precision Technology Co., Ltd.
2.Process	CNC Machining
3.Material	ADC12/A380
4.Surface	nickel plating
5.Tolerance	+/- 0.01mm
6.Quantity	1000 pieces
7.Specification	OEM service
8.Delivery Time	25-30 days
9.Accessories	accessories
10.Certification	Austrian EU
11.ISO 9001	
ISO 9001	
ISO 9001	
2. Quantity	
3. Surface	finishment kinds available
4. Lead Time	
5. Price	
6. Payment	
7. Shipping	
8. Quality	
9. ISO 9001	
10. OEM	
OEM	