

Inspection Report

Report No.: XYN-130820
Supplier : XY-GLOBAL

Inspection Date:11th Sep-, 2013
Inspector:LEO

Inspection only for: PO . XYN-130820 Item No.1403530	<u>Inspection Result:</u> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
1403530	6000PCS	1% inspection	0pcs	No failure	6000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing



2. Product:



3. Product:



4. Product:



5. Product :



6. Product:

	CNC CNC CNC CNC
	AL6061 AL6065AL6063AL7075 SUS304SUS303SUS316POM
	CNC
MOQ	
	+/- 0.01
	T / T 5050T / T
	CNC CNC CNC CNC
	20-25 T / T 50
	CNC
1.Name	OEM CNC
2.Process	CNC
3.	AL6061 AL6065AL6063AL7075POM
4.Surface	nickle
5.Tolerance	+/- 0.01
6.	100
7.Specification	OEM
8.	25-30
9.	CNC accessoried
10.	AustrialEU
11&NBSP	ISO 9001
ISO	110
2.	
3	surefacefinishment kindlsavailable
	4
5.	
	6
7.	
CNC	&NBSP
CNC	
CNC	ISO9001
CNC	
CNC	OEM