XY-GLOBAL **XY Electronics Technology Co., Ltd**

Inspection Report

Report No.: XYSL-130527
Supplier : **XY-GLOBAL**

Inspection Date:27th- Jun, 2013
Inspector: Leo

Inspection only for:	Inspection Result:
PO . XYSL-130527 Item No. XY11SL017	PASS

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY11SL017	18000PCS	5% inspection	0pcs	No failure	18000pcs

Appearance Inspection :
No failure,
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :

1. Packing

2. Product

3. Product

4 Product

5. Product:



6. The test report

□□□□□	□□□□ □□□□□