

Inspection Report

Supplier : XY-GLOBAL

Inspector: Leo

Inspector: Leo

Inspection only for: PO . XYKB-140518 Item No. XY72YM014	<u>Inspection Result:</u> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY72YM014	2000PCS	1% inspection	Opes	No failure	2000pcs

Appearance Inspection :

No failure.

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing



2. Product




3. Product



4 Product



5. Product:

[illegible]

6. Dimensions report:

Part Name	Part Name: ADC12 A380
Material	Material: ADC12 A380
Surface	Surface: nickel
Tolerance	Tolerance: +/- 0.01
MOQ	MOQ: 1000
Lead Time	Lead Time: 20-25 days
Payment	Payment: T/T 50% in advance, 50% before delivery
1.Name	1.Name: OEM
2.Process	2.Process: CNC
3.Material	3.Material: ADC12 A380
4.Surface	4.Surface: nickel
5.Tolerance	5.Tolerance: +/- 0.01
6	6: 1000
7.Specification	7.Specification: OEM service
8	8: 25-30 days
9	9: accessoried
10	10: Austrial EU
11	11: ISO 9001
ISO	ISO 1. 10
2	2: 10
3	3: sureface finishment kinds available
4	4: 10
5	5: 10
6	6: 10
7	7: 10
8	8: 10
9	9: 10
10	10: ISO9001
11	11: 10
OEM	OEM: 10