

Inspection Date: 15th July, 2014
Inspector: Leo

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31SY37	30000PCS	1% inspection	Opcs	No failure	30000pcs

The inspection sample plan is 100% inspection.

A large stack of cardboard boxes is shown in a warehouse setting. The boxes are stacked on a wooden pallet and are arranged in a way that shows multiple layers. The boxes are light brown and have some text and a logo on them. The background shows a warehouse floor and some other boxes or equipment.

1. Packing

2. Product



3. Product

4 Product

[illegible]

5. Product:

6. report

[illegible]