

Inspection Report

Report No.: XYA-130205
Supplier : XY-GLOBAL

Inspection Date: 24th Apr., 2013
Inspector:KEN

Inspection only for:	Inspection Result:
Item No: CA241-0208	PASS

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
CA241-0208	320000 PCS	500PCS	5pcs	No failure, with little flaws, acceptable	320000pcs

Appearance Inspection :
5pcs burrs and scratch on products surface, acceptable
Dimension Inspection:
No failure , refer to measurement report.
Assembly Test:
No failure
Inspection Summary
The inspection sample is 100% inspection.

Digital photo records :	
	
1. Packing	2. Packing
	
3. Packing	4. Packing
	
5. Product	6. Product
	
7. Product	8. Product
	
9. Inspection	10. Inspection
	
11. Inspection	12. Inspection

	CNC
	AL6061 AL6065AL6063AL7075 SUS304SUS303SUS316POM
	&NBSP;
	CNC
	gague
MOQ	
/	+/- 0.01
	T / T 50T / T
	CNC CNC CNC CNC
	CNC
	20-25&NBSP; T / T 50
	CNC
1.Name OEM CNC	
2.Process CNC	
3.AL6061 AL6065AL6063AL7075POM	
4.Surface nickle	
5.Tolerance +/- 0.01	
6.100	
7.Specification OEM	
8.25-30	
9.CNC accessoried	
10.Austrial EU	
11&NBSP;ISO 9001	
ISO110	
2	
3 sureface finishment kinds available	
4	
5	
6	
7	
CNC&NBSP;	
CNC	
CNC ISO9001	
CNC	
CNC OEM	