

Inspection Report

Report No.: XYWD-140626
Supplier: XY-GLOBAL

Inspection Date: 20th July, 2014
Inspector: Leo

Inspection only for: PO: XYWD-140626 Item No. XY31SY43	<u>Inspection Result:</u> PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31SY43	50000PCS	1% inspection	0pcs	No failure	50000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure, below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing

2. Product



3. Product

4 Product



XY-GLOBAL 深圳市真朴电子科技有限公司
XY Electronics Technology Co., Ltd

Customer: XY Electronics Technology Co., Ltd		Product Type: XY31SY43		Inspection Date: 2014.07.20	
Part No: XY31SY43		Lot No: 140626		Inspector: Leo	
Quantity: 50000PCS		Inspection Quantity: 500PCS		Pass Rate: 100%	
1. General Inspection: The product is in good condition, no obvious defects found. 2. Dimensional Inspection: The product dimensions are within the specified tolerance. 3. Surface Inspection: The product surface is smooth, no scratches or rust found. 4. Assembly Inspection: The product is assembled correctly, no loose parts found. 5. Final Inspection: The product is ready for shipment.					
Inspector: Leo Date: 2014.07.20					

5. Product:

6. report

[illegible]