

Inspection Report

Report No.: XYSK-140603
Supplier : XY-GLOBAL

Inspection Date: 2th July, 2014
Inspector: Leo

Inspection only for: PO . XYSK-140603 Item No. XY31SY003	Inspection Result: PASS
--	----------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31SY003	6000PCS	1% inspection	0pcs	No failure	6000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :

	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. report

	CNC
	AL6061 AL6065AL6063AL7075SUS304SUS303SUS316POM
	CNC
	gague
MOQ	
/	+/- 0.01
	T / T 50 50T / T;
	CNC CNC CNC CNC
	CNC
	20-25T / T 50
	CNC
1.Name OEM CNC	
2.Process CNC	
3.MaterialAL6061 AL6065AL6063AL7075 POM	
4.Surface nickle	
5.Tolerance +/- 0.01	
6 100	
7.SpecificationOEMserice	
8. 2530	
9. CNC accessoried	
10. AustrialEU	
11. ISO 9001	
ISO1. 10	
2.	
3. surefacefinishment kindlsavailable	
4.	
5.	
6.	
7.	
CNC	
CNC	
CNCISO9001	
CNC	
CNCOEM	