

Inspection Report

Report No.: XYSL-130521

Supplier : XY-GLOBAL

Inspection Date: 17th Jun, 2013

Inspector: Leo

Inspection only for: PO . XYSL-130521 Item No. XY11SL012	<u>Inspection Result:</u> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY11SL012	6000PCS	5% inspection	0pcs	No failure	6000pcs

Appearance Inspection :

No failure.

Dimension Inspection:

No failure, below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing



2. Product



3. Product



4 Product



5. Product:

θ	$\beta = 0.001, \alpha = 0.05$				
A	0.0000	0.0000	0.0000	0.0000	0.0000
B	0.0000	0.0000	0.0000	0.0000	0.0000
C	0.0000	0.0000	0.0000	0.0000	0.0000
D	0.0000	0.0000	0.0000	0.0000	0.0000
E	0.0000	0.0000	0.0000	0.0000	0.0000
F	0.0000	0.0000	0.0000	0.0000	0.0000
G	0.0000	0.0000	0.0000	0.0000	0.0000
H	0.0000	0.0000	0.0000	0.0000	0.0000
I	0.0000	0.0000	0.0000	0.0000	0.0000
J	0.0000	0.0000	0.0000	0.0000	0.0000
K	0.0000	0.0000	0.0000	0.0000	0.0000
L	0.0000	0.0000	0.0000	0.0000	0.0000
M	0.0000	0.0000	0.0000	0.0000	0.0000
N	0.0000	0.0000	0.0000	0.0000	0.0000
O	0.0000	0.0000	0.0000	0.0000	0.0000
P	0.0000	0.0000	0.0000	0.0000	0.0000
Q	0.0000	0.0000	0.0000	0.0000	0.0000
R	0.0000	0.0000	0.0000	0.0000	0.0000
S	0.0000	0.0000	0.0000	0.0000	0.0000
T	0.0000	0.0000	0.0000	0.0000	0.0000
U	0.0000	0.0000	0.0000	0.0000	0.0000
V	0.0000	0.0000	0.0000	0.0000	0.0000
W	0.0000	0.0000	0.0000	0.0000	0.0000
X	0.0000	0.0000	0.0000	0.0000	0.0000
Y	0.0000	0.0000	0.0000	0.0000	0.0000
Z	0.0000	0.0000	0.0000	0.0000	0.0000

6. The test report

[illegible]