

Inspection Report

Report No.: XYFA-140903

Supplier : XY-GLOBAL

Inspection Date: 5th Oct., 2014


Inspector: LEO

Inspection only for:	Inspection Result:
PO : XYFA-140903 Item No. XY21ZC060	PASS

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY21ZC060	5000pcs	7% inspection	0pcs	No failure	5000pcs

Appearance Inspection :
No failure,
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :

	
1. Packing	2. Product:
	
3. Product:	4. Product:
	
5. Product :	6. Inspection report:

[illegible]