

Inspection Date: 10th July, 2014
Inspector: Leo

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31SY014	10000PCS	1% inspection	0pcs	No failure	10000pcs

Appearance Inspection :
No failure,
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing

2. Product



3. Product

4 Product



5. Product:

6. report

	CNC
	AL6061 AL6065AL6063AL7075SUS304SUS303SUS316POM
	CNC
	gague
MOQ	
/	+/- 0.01
	T / T 50 50T / T;
	CNC CNC CNC CNC
	CNC
	20-25T / T 50
	CNC
1.Name	OEM CNC
2.Process	CNC
3.Material	AL6061 AL6065AL6063AL7075 POM
4.Surface	nickle
5.Tolerance	+/- 0.01
6.	100
7.Specification	OEMserice
8.	2530
9.	CNC accessoried
10.	AustrialEU
11.	ISO 9001
ISO	1. 10
2.	
3. sureface	finishment kindlsavailable
	4.
5.	
	6.
7.	
CNC	
CNC	
CNC	ISO9001
CNC	
CNC	OEM