

Inspection Report

Report No.: XYI-140322
Supplier : XY-GLOBAL

Inspection Date: 19th Apr, 2014
Inspector: Leo

Inspection only for: PO : XYI-140322 Item No.143045	Inspection Result: PASS
--	----------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
143045	6000PCS	1% inspection	0pcs	No failure	6000pcs

Appearance Inspection :

No failure.

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing



2. Product



3. Product



4 Product



5. Product:



6. Product:



7. Product:

8. Report:

品名	铝合金精密压铸加工件OEM加工
材料	ADC12/A380
数量	10000件
用途	汽车零部件
加工方法	CNC精密加工
表面处理	阳极氧化
公差	±0.01mm
MOQ	1000件
交货期	15天
包装	纸箱
认证	ISO9001
备注	
1.Name	铝合金精密压铸加工件OEM加工
2.Process	CNC精密加工
3.材料	ADC12/A380
4.Surface	阳极氧化
5.Tolerance	±0.01mm
6.数量	10000件
7.Specification	OEM加工
8.交货期	15天
9.包装	纸箱
10.认证	ISO9001
11.&NBSP	
ISO	9001
2.	
3.sureface	finishment
4.	
5.	
6.	
7.	
ISO	9001
2.	
3.sureface	finishment
4.	
5.	
6.	
7.	
ISO	9001
2.	
3.sureface	finishment
4.	
5.	
6.	
7.	