

Inspector: Leo

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31CY037	55000PCS	1% inspection	Opes	No failure	55000pcs

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing



2. Product



3. Product



4 Product



5. Product:



6. report

[illegible]