

Inspection Report

Report No.: XYWD-140628

Inspection Date: 25th July, 2014

Supplier: XY-GLOBAL

Inspector: Leo

Inspection only for: PO . XYWD-140628 Item No. XY31SY45	Inspection Result: PASS
---	----------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31SY45	30000PCS	1% inspection	0pcs	No failure	30000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.


Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :

	
1. Packing	2. Product
	
3. Product	4 Product
	 
5. Product:	6. report

[illegible]