

Inspection Report

Report No.: XYDN-140605

Inspection Date: 2th July, 2014

Supplier : XY-GLOBAL

Inspector: Leo

Inspection only for: PO . XYDN-140605 Item No.300-289	Inspection Result: PASS
---	----------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
300-289	2000PCS	1% inspection	0pcs	No failure	2000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :

			
1. Packing		2. Product	
			
3. Product		4 Product	
			
5. Product:		6. Product	

[illegible]